



SAFETY ALERT

No: SA 2022.01

Date: 18.05.2022

Subject: ELA 10-Eclipse pre-rotator assembly

Background

During a 200 hr inspection, the following crack was discovered in the rotor head assembly for the pre-rotator. All owners of the ELA 10-Eclipse in Australia have been advised by the Australian distributor, Rotor Sport, to inspect this area for any cracking. Owners and operators should include a thorough inspection of this location during their next pre-flight inspection of all gyroplane models.



ASRA Operations Manager

Jeff Blunt

E-mail: operationsmanager@asra.org.au

Mobile: 0421 784 088